

East Coast Railway

Office of the
Pr. Chief Commercial Manager
Bhubaneswar-751017
Dt- 17.03.2020
18

Commercial Circular No. 54 (G)/2020

Sub: Re notify of new eleven digit numbers of 03 Nos of Privately owned rakes of M/s Hindalco Industries Ltd. from the Loading point MUAT of ECoR

Ref : This office Commercial Circular No. 103 (G)/2019 Dt- 04.06.2019

1. Vide East Coast Railway's Commercial circular No. 103 (G)/2019 Dt- 04.06.2019, the approved route for movement of 03 Nos of Privately owned rakes by M/s Hindalco Industries Ltd. are as follows:

Station from	Station to
Hindalco Industries Ltd Siding, Muri (IACM) under DHN division of SER	1.Private siding of M/s Hirakud Industrial Works Ltd. (HIWS), Hirakud served by Sambalpur, SBP division of ECoR
	2.M/s Hindalco siding at Renukot (HACG) under ECR
	3.M/s Mahan Aluminium Smelter and Captive Power plant Siding (HIMB) served by Bargawan Station (WCR)
M/s Utkal Alumina International Siding, Tikri (MUAT) under ECoR	1.Private siding of M/s Hirakud Industrial Works Ltd. (HIWS), Hirakud served by Sambalpur, SBP division of ECoR
	2.M/s Hindalco Industries Ltd. siding at Renukot (HACG) under ECR
M/s Utkal Alumina International Siding, Tikri (MUAT) under ECoR	M/s Hindalco Industries Limited (unit-Aditya Aluminium) Code – MAAL served under ECoR

2. The list of wagon numbers was annexed as Annexure –A. Some old wagon numbers were converted to new eleven digit numbers. The list of converted new wagon numbers is attached as Annexure –A.
3. All other details of the Rates Circulars under reference will continue to apply unchanged.

All concerned to note and act accordingly.

Encl.- List of wagon numbers as Annexure-A

M
18/03/2020
(H.L.Luwang)

Dy Chief Commercial Manager (FS)

(Continue to Page 2)

No.CCM/POW/BTAP/Hindalco/Pt-I

dt 17.03.2020

All station Managers/Goods Supervisors/Commercial Supervisors/Siding Clerks/Booking Clerk in Charges/Weigh Bridge Clerks/Clerk in Charges/Commercial Inspectors.

Copy for information and necessary action to the :-

PCOM/ECOR, PCME/ECOR, CFTM/ECOR, SDGM/ECOR, FA&CAO(WST)/ECOR, Chairman/RCT/BBS, DyCVO(T)/ECOR, DyCOM(FOIS) /ECOR, PO/RCT/BBS, Audit Officer/BBS, Rates Section/CCM/ECOR/BBS-10 sets, DRM : KUR,WAT,SBP/ECOR, Sr DOM : KUR,WAT,SBP/ECOR, Sr DCM : KUR,WAT,SBP/ECOR, Dy CCO/ECOR, Traffic Manager: Visakhapatnam port Trust, Paradeep Port/Paradeep, M/s Vedanta Ltd

WAGON DETAILS OF PRIVATELY OWNED RAKES OF M/S HINDALCO INDUSTRIES LTD.

ANNEXURE - A

Rake Formation of BNT-3		Rake Formation of BNT-1		Rake Formation of BNT-2	
Sl. No.	New Wagon Number	Sl. No.	New Wagon Number	Sl. No.	New Wagon Number
1	46440860361	1	46440860309	1	46440860026
2	46440807779	2	46440860156	2	46440860051
3	46440809773	3	46440860255	3	46440860200
4	46440809667	4	46441160040	4	46440700094
5	46440760067	5	46441160019	5	46441001152
6	46441160293	6	46441001060	6	46441060067
7	46440860187	7	46440860354	7	46441160187
8	46440860286	8	46441060036	8	46441060104
9	46440807885	9	46440804006	9	46440860330
10	46441101517	10	46440860248	10	46441006005
11	46440808660	11	46440860149	11	46440860019
12	46440760074	12	46441160248	12	46441160125
13	46440860316	13	M-64	13	46440760180
14	46441160149	14	46441160101	14	46440860101
15	46440806772	15	46440700247	15	46441160156
16	46441060074	16	46440860064	16	46440760135
17	46440806116	17	46441160347	17	46441160163
18	46440860057	18	46441160286	18	46440860118
19	46440860293	19	46441001206	19	46441060135
20	46440805669	20	46440760128	20	46440801012
21	46440807335	21	46441160231	21	46440760081
22	46441101289	22	46440860279	22	46440805225
23	46441060323	23	46441160279	23	46440801036
24	46441101395	24	46440804990	24	46440760241
25	46440802996	25	46441060043	25	46441001107
26	46440760166	26	46441060111	26	46440860170
27	46441160071	27	46440700032	27	46440808998
28	46441101487	28	46441060029	28	46440804778
29	46441160262	29	46441160095	29	46440760098
30	46440860347	30	46441160200	30	46441060012
31	46441160057	31	46440860217	31	46440806222
32	46440760104	32	46440803559	32	46440803443
33	46441160309	33	46440860378	33	46440760227
34	46440760142	34	46440760210	34	46440805447
35	46440760203	35	46440803009	35	46440807441
36	46441160170	36	46441160026	36	46440803115
37	46440860095	37	46441160224	37	46441160217
38	46441101241	38	46440808004	38	46440808776
39	46440804440	39	46440805881	39	46440860163
40	46441060128	40	46441160323	40	46441060081
41	46440860194	41	46440808110	41	46441160064
42	46440760234	42	46440860125	42	46440804228
43	46440860231	43	46440760029	43	46440760043
44	46440860224	44	46441160255	44	46440860033
45	46441160330	45	46440860262	45	46441160316
46	46440706173	46	46440760036	46	46440760159
47	46440760197	47	46440809551	47	46440806000
48	46440801043	48	46440806994	48	46440804334
49	46441160118	49	46440809889	49	46440860040
50	46441160033	50	46440809117	50	46440860132
51	46440809551	51	46441060098	51	46441160132

Spare Wagon details:-
46440808882, 46440809995, 46441060050, 46441160194, M-76, 46440860088

forwrded to
SSE/G/C&W/BNM.
AK/ma
21/02/2020.

के एस. शर्मा
21/02/2020
गारम अनुभाग अधिकारी (स.मा.क)
दक्षिण पूर्व रेलवे, बम्बारावा
Senior Section Engineer (C & W)
S. B. Rly. Baramunda

