

EAST COAST RAILWAY

Office of the
Principal Chief Commercial Manager
1st Floor, Rail Sadan
C.S.Pur, Bhubaneswar-17

Commercial Circular No.327(G)/2022

Date:0310.2022

Sub: Running of trains with Mixed Composition of BOXNHL25T with BOXN group of wagons.

A copy of Railway Board's letter No.TCR/1017/BOXNHL25T-BOXN/3405333 dated 30.09.2022 regarding "Running of trains with Mixed Composition of BOXNHL25T with BOXN group of wagons" is enclosed herewith for information and necessary action.

All concerned to note and act accordingly.

Authority:Railway Board's letter No. TCR/1017/BOXNHL25T-BOXN/3405333 dated 30.09.2022

Encl: As above (one page).


(Anil Kumar S)
Dy.Chief Commercial Manager(FS)


No. PCCM/356/Policy/PCC/Pt.X

Date 03.10.2022

All Station Managers/ Goods Supervisors/Commercial Supervisors /Siding Clerks / Booking Clerk in Charges / Weigh Bridge Clerks / Clerk in Charges / City Booking Agencies / Out Agencies.

Copy for information and necessary action to the:-

COM: ECoR/SER/SECR/NR/NFR/ER/SR/SCR/WR/NER/CR/SWR/NCR/NWR/WCR/ECR/KRly.. **SDGM**/ECoR/BBS, **Chairman**/RCT/BBS, **Dy.CVO**/ECoR/BBS, **Dy.COM(FOIS)**/ECoR/BBS, **PO/RCT**/BBS, **CAO(FOIS)**/NDLS, **Audit officer**/BBS. Rates Section /CCM/ECoR/BBS -10 sets **DRM:** KUR,WAT,SBP/ECoR, **Sr.DOM-** KUR,WAT,SBP/ECoR, **CAO(FOIS)**, CRIS/NDLS **Sr.DCM:** KUR,WAT/SBP/ECoR. **Dy.CCM(Claims)**/E.Co.Rly, **FA & CAO:** E.Co.Rly, **FA & CAO(T)**/ECoR/BBS **Traffic Manager:** VZP, Paradeep Port Trust / Paradeep.


(Anil Kumar S)
Dy.Chief Commercial Manager(FS)

02 Pages

①

भारत सरकार GOVERNMENT OF INDIA
रेल मंत्रालय MINISTRY OF RAILWAYS
(रेलवे बोर्ड RAILWAY BOARD)

No.TCR/1017/BOXNHL25T-BOXN/3405333

Dated : 30.09.2022

**General Manager,
All Zonal Railways.**

Sub: Running of trains with Mixed Composition of BOXNHL25T with BOXN group of wagons.

It has been brought into knowledge of Board, that due to operational constraints and/ or to avoid short running of rakes, it is not possible to run pure BOXNHL25T rake and BOXN group of wagons are mixed with BOXNHL25T wagons and vice-versa, and requested that mixed rake may be allowed through system.

Matter has been examined and it is noticed that mixed rake will require speed restrictions, therefore, advised that BOXNHL25T rakes should be strictly segregated and run as 25T axle load. However, if any rake is moved in mixed condition, it will be loaded and charged as 22.9 ton Axle Route.

This issues in consultation with Mechanical and Traffic Transportation Directorates of Ministry of Railways.

(This disposes off East Coast Railway's letter No.PCCM/356/policy/PCC/Pt.IX/982 dated 13/08/2022).


(Anshoo Pandey)
Director, Traffic Commercial (Rates)
Railway Board.
dtcr@rb.railnet.gov.in
011- 2304 7359

Copy to :

1. Managing Director/CRIS, CRIS Complex, Chanakyapuri, New Delhi-110021.
2. CAO/FOIS, CRIS Complex, Chanakyapuri, New Delhi-110021.

SL No. 327(G)/2022

2

Rail Bhavan, Raisina Road, New Delhi-110001. रेल भवन, रायसीना रोड, नई दिल्ली -110001.

02 pages