

will continue 5

CE's CIRCULAR No.03

JOINT CIRCULAR ON PERIODIC MEASUREMENT OF HORIZONTAL DISTANCE TO THE
SIGNALLING STRUCTURES

Dated : August 13, 2003

CE's File No.W.7/636/Pl.I 9004

CE's Circular No.03
CSTE's Circular No.03

In order to avoid infringement of signal posts/part of signal posts to the moving trains, following should be implemented immediately in the divisions.


- i) Implantation distance should be prominently painted by the Signaling Department on signal posts for guidance of P.Way and signaling officials. ✓
- ii) While carrying out tamping operations, supervisor in charge of track machine viz. Machine Foreman and the Sectional PWI should ensure no infringement to signals due to erroneous slewing of track. ✓
- iii) Implantation distance of the signal posts mentioned in the item (i) above should be recorded in the quarterly joint inspection register of turn outs as per enclosed format. During quarterly joint inspections, Signal and P.Way Inspectors should measure the prevailing signal implantation distance also. ✓
- iv) Wherever infringements are noticed, the PWI shall ensure immediate action in rectification of the same. ✓

The pages pertaining to signaling implantation as enclosed shall be incorporated in the Joint Inspection Register and shall be printed in future.

Encl : Format

V. Balaram
14.8.2003
(V.Balaram)

Chief Signal & Telecom.Engineer


13.8.03
(K.Gangopadhyay)
Chief Engineer

To
All HODs & Dy. HODs
Sr.DEN(Co)/KUR/SBP/WAT

Dy CE / Tr

JE/Team
Seen
may be filed.


21/8/03