

पूर्व तट रेलपथ EAST COAST RAILWAY
(सतर्कता विभाग VIGILANCE DEPARTMENT)



महाप्रबंधक (सतर्कता) का कार्यालय
प्रथमतल, रेलसदन, चंद्रशेखरपुर, भुवनेश्वर-17
Office of the General Manager (Vigilance)
1st Floor, Rail Sadan,
Chandrasekharpur, Bhubaneswar- 17,
Fax No. : BSNL: 0674-2301328, Rly.: 50702

No: ECoR/V-3/S&T/PC/186/2021/1866

Dated: 13.07.2022

To,
The Principal Chief Signal and Telecom Engineer,
East Coast Railway.
Rail Sadan, Bhubaneswar.

Sub: System improvement in AMC of IPS Equipment

From a series of vigilance checks carried out over different divisions of ECoR pertaining to AMC of IPS equipments, the followings are noticed.

- 1) The periodical visit maintenance checklist records followed in different divisions are not uniform. The comparison is listed below.

AMC visit Record Format	KUR Division	SBP Division	WAT division
No. of pages	5	3	1
Signature available at the bottom of each page	NO	Yes (at the bottom of each module)	Yes (only single page)
Details of Checking to be done by service engineer	Available	Available	Not Available


- 2) The list of qualified maintenance engineer/technician posted at various locations of the division as specified in the tender document is not available in the office of Sr.DSTEs.

The following improvements are suggested for better execution of the AMC maintenance work.

- 1) The checklist for periodical preventive maintenance of IPS should be uniform for all the 3 divisions.
- 2) "The firm should submit the list of qualified maintenance engineer/technician with their mobile number to the office of Sr. DSTE before execution of the contract" – This is to be implemented in the tender document of all AMC contracts.

The action taken in this regard may please be intimated to this office.

This issues with the approval of SDGM/ECoR.


13.7.2022
Samir Kumar Mohapatra
(समीर कुमार महापात्र)
Deputy Chief Vigilance Officer (S&T)
उपमुख्य सतर्कता अधिकारी (सी.एच.द.)
for General Manager (Vig)
कृते महाप्रबंधक (सतर्कता)