

VA - 2022/32

पूर्वतट रेलवे / EAST COAST RAILWAY
सतर्कता विभाग / VIGILANCE DEPARTMENT

महाप्रबंधक सतर्कता का कार्यालय
प्रथमतल, रेलसदन, चंद्रशेखरपुर, भुवनेश्वर.-17
Office of the General Manager (Vig)
1st Floor, RailSadon,
Chandrasekharpur, Bhubaneswar- 17.

No- GMV/ECOR/V3/241/2020/ 2267

Dt. 18.08.2022

To

The Principal Chief Engineer
East Coast Railway
Bhubaneswar

Sub: Use standard materials in building maintenance

During a vigilance investigation into a complaint on use of non standard and non approved materials in flooring of residential building, it was found that non prescribed flooring materials were used by the concerned SSE/Works on the verbal instructions of Sr. DEN concerned. Neither the concerned Sr.DEN has given any follow up written instruction nor the concerned SSE/W processed for regularization through noting. Also it may be noted that the materials used were received from other department where in it was seen that the materials procured originally were not for building maintenance purpose.

This was considered as highly irregular as this sort of practice will bring in disparity & comparison among quarter occupants.


Hence following systemic improvements are recommended.

1. No material, other than those defined in standard specification of updated manuals/ circulars/ PCE guide lines should be adopted for use in any Railway structures.
2. In case, any deviation from above/ new material is brought for use, the same should be with prior approval of competent authority.

Violation of above recommendation will render the executing designatory solely responsible.

Officers issuing such verbal instructions in emergent situations without follow up written instruction as per standard procedure will not be appreciated.

This issues with the approval of SDGM/ECOR/BBS.


(Pritiraj Panigrahi)
Dy. Chief Vigilance Officer (Engg.)
East Coast Railway
Bhubaneswar