

**East Coast Railway**  
**Engineering Department**  
**CE Circular No. 01/2023 dt. 13/01/2023**

**Sub: Protective screen for OHE on FOB/ROB.**

Protective screens are provided on FOB/ROB. It has been noticed that in some of the cases these protective screens are fixed outside of the FOB/ROB, which may result into, its falling on OHE wires.

In view of the above, it is advised that the protective screens on FOB/ROB must be kept inside of the FOB/ROB to protect it from falling on OHE wire/track and has to be inspected frequently and necessary repairs etc. to be carried out promptly. RDSO drawing No. ETI/C/0068 for protective screens shall be referred for further details in this matter.

This issues with the approval of PCE.

  
13-01-2023

(S. Y. Mendhekar)

**Chief Engineer/Works/BBS**

o/c

Dt. 13.01.2023

No. W4/374/C. E's circulars/Pt.II/ 297

Copy forwarded to:

1. Secy. to GM for kind information of GM.
2. All PHODs/CHODs
3. CAO(Con)/BBS
4. DRM/KUR, SBP & WAT
5. Sr.DEN(Co-Ord)/KUR, SBP & WAT
6. ED/RVNL/BBS
7. GM/IRCON/BBS
8. GM/RITES/BBS
9. GGM/IPRCL/BBS