

EAST COAST RAILWAY

Office of the
Principal Chief Commercial Manager
Bhubaneswar-17
Date 04.10.2024

Commercial Circular No. 334(G)/2024.

Sub: Separate Alpha & Numerical Code for SILO at Spur - 3 & 4 of Jagannath Washery siding of M/s Mahanadi Coalfields Limited, Talcher.

Ref: Commercial Circular No. 137(G)/2011 dt.19.12.2011 and No. 237(G)/2023 dt.21.08.2023.

South Balanda - Jagannath Colliery siding (Spur-1, 2, 3 & 4) of M/s. Mahanadi Coalfields Limited (Alpha Code: SBCT, Numerical Code:12121107) served by Talcher station (TLHR) over Khurda Road Division was notified open for outward traffic of Coal. The distance for charging of traffic was revised vide Commercial Circulars under reference as Talcher station (TLHR) + 19 Km and Entry point to MCRL from Balaram siding (EPMM) + 13.77 Km.

The loading spurs of the siding had been segregated and separate Alpha & Numerical Codes allotted vide Commercial Circular No. 321(G)/2024 dt.20.09.2024.

Consequent upon commissioning of SILO at Spur - 3 & 4 of Jagannath Washery siding, the loading spur is further segregated and separate Alpha & Numerical Codes allotted as follows:

Sl. No	Name of Siding	Alpha Code	Numerical Code
1	SILO at Spur - 3 & 4 of Jagannath Washery siding of M/s Mahanadi Coalfields Limited	SJWT	12121159

Free time of 3.00 hours for loading of Coal permitted vide this office's Memorandum No.PCCM/337/Freetime/Pt-III(Part)/321 dated 12.03.2021 for the traffic handled at the above siding will remain unchanged till further order.

The distances for charging of traffic for the above siding will remain unchanged as Talcher station (TLHR) + 19 Km and Entry point to MCRL from Balaram siding (EPMM) + 13.77 Km.

All other terms and conditions notified earlier will remain unchanged.

These instructions will come into effect from 05.10.2024.

All concerned to note and act accordingly.

(Preeti Rana)
Dy. Chief Commercial Manager (FS)

No. PCCM/F/Sdg/MCL/Jagannath/TLHR/Pt.-III.

Date 04.10.2024

Copy to:

All Station Managers / Goods Supervisors / Commercial Supervisors / Siding Clerks / Booking Clerks in Charges / Weigh Bridge Clerks / Clerk in Charges.

Copy for information and necessary action to the -

PCOM ECoR/SER/SECR/NER/NFR/ER/SR/SCR/WR/NER/CR/SWR/NCR/NWR/WCR/ECR/KRly.
PCCM SER/SECR/NER/NFR/ER/SR/SCR/WR/NER/CR/SWR/NCR/NWR/WCR/ECR/KRly.
SdGM/ECOR/BBS, Chairman/RCT/BBS, Dy.CYO(T)/ECOR/BBS, Rates Section /CCM/BBS -10 sets,
Dy.CCM(Claims)/ECOR, Dy.COM(EQIS)/ECOR/BBS, PO/RCT/BBS, CFTM/ECOR/BBS, 3PDA/BBS,
DRM KUR,WAT,SBP/ECOR, Sr.DCM KUR,WAT,SBP/ECOR, Sr.DCM KUR,WAT,SBP/ECOR, PFA/ECOR,
Traffic Manager VZP/VSKP, Traffic Manager PPT/PRDP, CAO(EQIS)/NDLS, DTT(GYRly Bd/NDLS,
JDTG(RyRly Bd/NDLS, Executive Director/CRIS/NDLS, Director (Rail Movement)/KOL.