



EAST COAST RAILWAY

प्रधान मुख्य कार्मिक अधिकारी का कार्यालय/
Office of the Principal Chief Personnel Officer
रेल सदन, द्वितीय तल, भुवनेश्वर - 751017
Rail Sadan, IInd Floor, Bhubaneswar-751017

स्थापना क्रमांक/ Estt. Srl. No.159/2019

पूतरे/कार्मिक/आर/ECOR/Pers/IR/Misc.

Date: 15.07.2019

सेवा मे,

सभी प्रमुख विभागाध्यक्षों/सामन्वयक विभागाध्यक्षों, पू त रे/भुवनेश्वर
मं.रे.प्र/व.मं.का.अधिकारी/मं.का.अधिकारी-खोरधारोड,वालातेरू, संबलपुर,
मु;कारखाना प्रबंधक/कारखाना कार्मिक अधिकारी-मंचेश्वर, अतिरिक्त रजिस्ट्रार/रेल दावा अधिकरण,
व.का अधिकारी(नि)/भुवनेश्वर
महा सचिव/इकोर श्र. कां., महा सचिव/इकोर श्र. यू.,
महा सचिव/एआई जो बी सी आर ई ए, महा सचिव/ ए आई एस सी एस टी आर ई ए

Sub: Revised instruction for Inspection by officers.

उपर्युक्त विषय पर पूर्व तट रेलवे पत्र सं. ECoR/SFY/Inspection/316 दिनांक 05.07.2019 की प्रतिलिपि सूचना. मार्गदर्शन एवं आवश्यक कार्रवाई हेतु अग्रेषित है।

A copy of the ECoR's Lr. No- ECor/SFY/Inspection/316 dated 05.07.2019 on the above quoted subject is forwarded herewith for information, guidance and necessary action.

Encl: As above,


(G.Sathy)

Dy.Chief Personnel Officer(IR&W)
For Principal Chief Personnel Officer

प्रतिलिपि प्रेषित/Copy to :

- 1) महाप्रबंधक के सचिव/पूर्व तट रेलवे, भुवनेश्वर
- 2) मुकाधि/मुकाधि(प्रशा.), उप म.प्र. अध्यक्ष(रेलवे भर्ती प्रकोष्ठ)
- 3) उप मुख्य प्रबंधक(सू.प्रौ). उप मुकाधि(औ.सं.एवं कल्याण), वकाधि(इंजी.)
- 4) वकाधि(स्टाफ), वकाधि(मुख्या. एवं न्याया.)
- 5) मुकाधि के निजी सचिव/सहा.कार्मिक अधि.(मुख्या.),सहा.कार्मिक अधि.(कल्याण), सहा.कार्मिक अधि.(बिल),

373
8/3/19

05/07/19
Pr. Chief Safety Officer
Bhubaneswar
10/02



EAST COAST RAILWAY

Office of the
Pr. Chief Safety Officer
Bhubaneswar

Date: 05.07.2019

No. ECoR/SFY/ Inspection / 316

To
The PCOM, PCE, PCME, PCEE, PCCM, PCSTE, PCPO, PFA, PCMD, PCMM & PCSC

&
The Divisional Railway Managers
KUR / WAT / SBP
East Coast Railway

Deco-72
Cpoch
R.L.
8/7

Sub: Revised instruction for Inspection by Officers.

Ref- (i) Secy. to GM Ir. No. ECoR/GA/Secy/Inspn./2019-20/188 dated- 28.06.19.

(ii) This office Ir.no. ECoR/SFY/ Inspection/310 dt. 03.07.19

On the above subject, following are the instructions of the GM, ECoR.

"That every officer in ECoR will do at least 02 nos. of surprise inspections in every month, out of which 01 no. will be in night between 02:00hrs to 04:00hrs. Place and time the officer will choose himself. Officers are however, free to do as many inspections as they consider necessary to discharge their duties effectively.

A gist of these 02 nos. inspections of each officer from all officers of your department/division should be compiled in one table department wise/division wise as per the format given below."

Same should be submitted to this office by 05th of the subsequent month for appraising to the GM.

S.N.	Name of Officer	Designation	Place & time of inspection	Shortcomings/ Wrong practices noticed

In view of above, the regular programmed night footplate inspections by HQ officers are discontinued forthwith.

[Signature]
Pr. Chief Safety Officer
Bhubaneswar

Copy to: 1- Secy. to GM for kind information of GM.
2- Secy. to AGM for kind information of AGM.



Office of the
Pr. Chief Safety Officer
Bhubaneswar

No.ECoR/SFY/ Inspection /310

Date:03.07.2019

To

The PCOM, PCE, PCME, PCEE, PCCM, PCSTE, PCPO, PFA, PCMD, PCMM & PCSC
&

The Divisional Railway Managers
KUR / WAT / SBP
East Coast Railway

B. S. Mishra
CPO(*)
8/3/19

Sub: Inspection by Officers.

Ref:-Secy. to GM Ir. No.ECoR/GA/Secy/Inspn./2019-20/188 dated-
28.06.19

GM, ECoR has instructed that every officer in ECoR will do at least 02 nos. of surprise inspections in every month, out of which 01 no. will be in night between 02:00hrs to 04:00hrs. This is apart from the mandated inspection as per extant instruction.

A gist of these 02 nos. inspections of each officer from all officers of your department/division should be compiled in one table department wise/division wise as per the format given below. Same should be submitted to this office by 05th of the subsequent month for appraising to the GM.

S.N.	Name of Officer	Designation	Place & time of inspection	Shortcomings/ Wrong practices noticed

In view of above, the regular programmed night footplate inspections by HQ officers are discontinued forthwith.

B. S. Mishra
3.7.19
Pr. Chief Safety Officer
Bhubaneswar

Copy to: 1- Secy. to GM for kind information of GM.
2- Secy. to AGM for kind information of AGM.