

EAST COAST RAILWAY

Office of the
Principal Chief Commercial Manager
Bhubaneswar-17
Date: 04.06.2020

Commercial Circular No. 124(G)/2020.


Sub: Separate Code for SILO SPUR of Balaram siding of MCL.

Commissioning of Rapid Loading SILO in the Balaram siding (Spur-9) of M/s. MCL served by Talcher station of Khurda Road Division was notified vide this office Commercial Circular No. 115(G)/2015 dtd. 04.09.2015.

Now with the approval of competent authority, to have flexibility in operation and loading, SILO SPUR of Balaram siding of MCL has been allotted separate Alpha and numerical Code as follows: **Alpha Code – SSMT Numerical Code: 12121125.**

The SILO SPUR of Balaram siding of MCL served by Talcher station is hereby notified as a full rake handling point for outward Coal traffic on through distance charging basis reckoning chargeable distance as **TLHR + 19.0 Km.**

All concerned to note and act accordingly.


(H. L. Luwang)

Dy. Chief Commercial Manager (FS)

PCCM/FS/Sdg/SILO Spur of Balaram/TLHR/Pt.-I


Date: 04.06.2020

Copy to:

All Station Managers / Goods Supervisors / Commercial Supervisors / Siding Clerks / Booking Clerks in Charges / Weigh Bridge Clerks / Clerk in Charges / City booking Agencies .

Copy for information and necessary action to the:

PCOM & PCCM: All Indian Railways, SDGM / ECoR, Dy. CVO (T) / ECoR, PO-RCT/BBS, Dy.COM (FOIS) / ECoR/BBS, CAO(FOIS) / CRIS/NDLS, Audit Officer / BBS, Dy. CCM(C& R), / ECoR, DRM, KUR, SBP, WAT. Sr. DCM & Sr. DOM / KUR, SBP, WAT. PFA / ECoR, Traffic Manager / PPT & VPT, DTT(G) & EDTC(R), Rly. Board/NDLS, CAO (FOIS) / CRIS / NDLS, Director (RM)/KOL.


(H. L. Luwang)

Dy. Chief Commercial Manager (FS)