

250

EAST COAST RAILWAY

Office of the
Principal Chief Engineer
North Block, Rail Sadan,
Chandrasekharpur,
Bhubaneswar- 751017.

No. W1/162/Drg/Siding Maint/ 6451

Dt 29.12.2020.

To
Sr. DEN (Co-ord)
East Coast Railway. KUR, SBP & WAT.

Sub:- Maintenance of Private Sidings in East Coast Railway.

Ref:- GM/ECOR's Review meeting on siding matters on 24.08.2020.

In the format issued for Private siding agreements in Freight Marketing Circular no. 11 of 2016, no criteria for engagement of Railway approved contractor or consultant as maintenance agency is mentioned for maintenance of siding in their land premises. The Siding owners, who are maintaining their siding alignment on their own; are engaging contractors at their consideration only, Lack of sufficient experience/expertise of these agencies towards maintenance of railway tracks is being considered as a major factor for derailments/accidents in sidings. This is not only causing damage to railway infrastructure but also affecting the loading of Railways.

During the review meeting taken on 24.08.2020, GM/ECOR had advised to issue necessary modification to Siding agreement for engaging Railway approved contractors/ consultants by Siding holders for the maintenance of siding alignments. Accordingly Railway Board is being requested to issue necessary modification to the proforma for siding agreement in this line.

Till the time such modified proforma is issued by Board, GM had instructed to advise list of proven contractors to sidings to outsource maintenance work to one of them only.

In view of above, you are advised to circulate the list of approved/proven P. Way contractors to the sidings under your Division and advise them to engage maintenance contractors from the list only.

Av
29/12
(G.H. Victor Joseph)
Chief General Engineer

Details of Charges for maintenance of Private Siding per KM per year.

As on 01.07.2020.

SL	Description	Track Maintainer Gr.IV to Gr.II Earlier Trackman L-1,2 & 4	Track Maintainer Gr.I Earlier Keyman L-5	Track Maintainer Gr.I Earlier Mate L-5	Track Maintainer Gr.IV to II Eariler Trolley man L-1,2 & 4	SSE(P.Way) L-7
1	No. of men required	1.2	0.2	0.2	0.33	0.083
2	Average pay (Rs. Per Month)	52920	12150	12150	14553	7773
		(Avg mean pay= 44100x1.2)	(Avg mean pay= 60750x0.2)	(Avg mean pay= 60750x0.2)	(Avg mean pay= 44100x0.33)	(Avg mean pay= 93650x0.083)
3	DA (@ 17% as on 01.01.2020) of SL-2	8996	2066	2066	2474	1321
4	Total	61916	14216	14216	17027	9094
5	Leave Salary @11%of Sl.4	6811	1564	1564	1873	1000
6	PF & Gratuity @1/8 of (Pay +1/11 of pay)	7216	1657	1657	1985	1060
7	Incidental charges 10% @ (pay+1/11 of pay)	5773	1325	1325	1588	848
8	Total (Rs. Per month)	81716	18762	18762	22473	12002
9	Annual (Rs)	9,80,592	2,25,144	2,25,144	2,69,676	1,44,024
	Annual Total					18,44,580
10	Tools & Plants (Lumpsum)					20,000
11	Cost of replacement of small fittings like ERCs, Rubber pads, Liners, Keys, Coters, Spikes, Fish Bolts, Fish Plates etc.,@ 3% of the cost of fittings (For PSC/CST-9 sleepers with M+4 density and present cost of fittings = Rs 7,52,000 approx.)					22,560
12	Total					18,87,140
13	Departmental charges 12.5%					2,35,893
14	Total Annual maintenance charges per Km					21,23,033
15	Per month maintenance charges per Km					1,76,919.42

Details of Inspection charges for Private sidings by Railways per KM per year

As on 01.07.2020.

SL	Description	Track Maintainer Gr.IV to Gr.II Earlier Trolleyman L-1,2 & 4	SSE(P.Way) L-7
1	No. of men required	0.016	0.004
2	Average pay (Rs. Per Month)	706	375
		(Avg mean pay= 44100x0.016)	(Avg mean pay= 93650x0.004)
3	DA (@ 17% as on 01.01.2020) of SL-2	120	64
4	Total	826	439
5	Leave Salary @11%of Sl.4	91	48
6	PF & Gratuity @1/8 of (Pay +1/11 of pay)	96	51
7	Incidental charges 10% @ (pay+1/11 of pay)	77	41
8	Total (Rs. Per month)	1090	579
9	Annual (Rs)	13,080	6,948
	Annual Total		20,028
10	Trolley, Tools & Plants (Lumpsum)		2,000
11	Total		22,028
12	Departmental charges 12.5%		2,753.5
13	Total Annual Inspection charges per Km		24,781.5
14	Per month Inspection charges per Km		2,065.13

Vetted

Ar
मुख्य सामान्य अभियन्ता
Chief General Engineer
भवनेश्वर

N. S. Dary
13/11/2020
For FA & CAO/E.Co.Rly/BBS