

21-2020

पूर्व तट रेलपथ EAST COAST RAILWAY
(सतर्कता विभाग VIGILANCE DEPARTMENT)

महाप्रबंधक(सतर्कता) का कार्यालय
प्रथमतल, रेलसदन, चंद्रशेखरपुर, भुवनेश्वर-17
Office of the General Manager (Vig)
1st Floor, Rail Sadan,
Chandrasekharpur, Bhubaneswar- 17,
Fax No. : BSNL: 0674-2301328, Rly.: 50702

No: ECoR/V-3/S&T/PC/RPF/08/ 2930

Dated: 20.11.2020

To

All PHODs/CHODs: PCE,PCEE,PCOM,PCMM,PCCM,PCSTE,PCPO,PCSO, PFA,
PCME,PCMD & CAO/Con,
East Coast Railway.


All DRMs: DRM/SBP, WAT& KUR
CWM/MCS,
East Coast Railway.

Sub: System improvement advice to ensure authentic and valid RDSO/RITES Inspection certificate.

During investigation of a Vigilance case on supply of materials, it was found that a contractor had supplied materials with fake RITES Inspection certificate. In this connection, it is recommended by Railway Board to issue following System improvement advice to ensure authentic and valid RDSO/RITES Inspection certificate.

- Executive shall ensure authenticity and validity of Inspection certificate issued by RDSO/RITES by making written correspondence with the inspecting agency or through website of RDSO/RITES.
- Before issue of call letter to RDSO/RITES, readiness of materials for inspection is to be ascertained.
- Validity of Inspection call letter is to be specified and should be reasonable.
- Contractor should produce manufacturer's / authorized supplier's original challan, test report if any, road challan etc. along with the materials to avoid reoccurrence of this type of events.

Action taken in this regard may be intimated to this office.


(R.K.Panda) 20.11.2020

Dy. Chief Vigilance Officer (S&T)
For Sr.Deputy General Manager
East Coast Railway; Bhubaneswar