



पूर्वतट रेलवे
EAST COAST RAILWAY
(सतर्कता विभाग)

महाप्रबंधक (सतर्कता) का कार्यालय
प्रथमतल, रेलसदन, चंद्रशेखरपुर, भुवनेश्वर.-751017
Office of the General Manager (Vig)
1st Floor, Rail Sadan,
Chandrasekharpur, Bhubaneswar- 751017.

(2021/04)

No: ECoRV-3/S&T/PC/219/20/ 1298

Dt.01.06.2021

To,
The Principal Chief Signal and Telecom Engineer,
East Coast Railway.

Sub: Inclusion of correct specification of material for procurement.

During a preventive check on consignee inspected telecom materials in the store of SSE/Tele/Project/BBS, fiber termination box was found not as per standard railway specification. These fiber termination boxes were procured vide item number 16 of schedule-A of contract agreement number S&T/Proj/BBS/CCTV/OT/03/2015/CA dated 17.11.2015. There is no mention of specification, Make and model, capacity of fiber accommodation and type of fiber terminals in the fiber termination box.


Due to the faulty schedule (without any specification), genuine material is not received by railway.

The material supplied is an unknown make cable termination without any terminal.

In view of the above, the following advice may be issued to all S&T units with intimation to this office.

"To ensure quality of material correct specification of materials and its availability may be ensured while framing a tender schedule or a requisition to stores."

This has the approval of SDGM/ECoR.


01.06.2021
(R.K.Panda)

Dy. Chief Vigilance Officer (S&T)
For Sr. Deputy General Manager
East Coast Railway; Bhubaneswar