



पूर्वतट रेलवे
EAST COAST RAILWAY
(सतर्कता विभाग)
Vigilance Department

महाप्रबंधक (सतर्कता) का कार्यालय
प्रथमतल, रेलसदन, चंद्रशेखरपुर, भुवनेश्वर.-751017
Office of the General Manager (Vig)
1st Floor, Rail Sadan,
Chandrasekharpur, Bhubaneswar- 751017.

(2021/18)

No: ECoR/V-3/S&T/PC/438/21/ 3233

Dt. 24.12.2021

To,
The Sr. DSTE/WAT,
East Coast Railway.

Sub: System improvement regarding maintenance of store.

A preventive check was conducted on the maintenance of store record of SSE/Sig/SUP. During this check, the following irregularities were found.

1. The controlling officer has not been inspected the store of SSE/Sig/SUP.
2. The proposal of condemnation was given by SSE/Sig/SUP on 05.12.2020, but no action has been taken by Sr. DSTE/WAT office till date.


In view of the above, it is advised to ensure the inspection of the store of the stock holder by the respective controlling officer at least once in a year.

It is also advised to process the condemnation proposals given by the stock holders and dispose the scraps in a time bound manner to avoid further accumulation of scrap in the stores.

Action taken against this system improvement may be intimated to this office at the earliest.

Please treat the matter as most urgent.

This has the approval of SDGM/ECoR.


24.12.2021
Rajendra Kumar Panda
(राजेन्द्र कुमार पण्डा)

Deputy Chief Vigilance officer (S&T)
उपमुख्य सतर्कता अधिकारी(सी.एब.दु.)
East Coast Railway, Bhubaneswar
पूर्वतट रेलवे, भुवनेश्वर

o/c