



CONFIDENTIAL

**EAST COAST RAILWAY
Office of the General Manager
(VIGILANCE)**

1st Floor, E. Co. Rly. Headquarters, Bhubaneswar-17, Fax: BSNL: (0674) 2301320, Rly: 50702

No. GM/Vig/ECOR/Advisory/29/2022 | 2360

Date:-29.08.2022

Vigilance Advisory No.2022/29

To,

The Principal Chief Mechanical Engineer,
East Coast Railway,
Bhubaneswar.

Sub: Advisory related to out sourced work of "Heavy repair of unloadable BOXN wagon".

During vigilance check at wagon depots of OEC/VSKP and CSL/VSKP, following irregularities are noticed:

1. Measurement sheets are computer generated loose sheets without any machine printed serial number and prone to manipulation.
2. Timely disposal of scraps are not being done by the firm leading to accumulation of huge amount of scrap.
3. Few wagons were found to be available at CSL/WAT for repair, but were not offered to the firm as pre-inspection was not done, which leads to detention of wagons.

In view of the above, the following improvements are suggested for better execution of the contractual works:

1. Hard bound register for measurements instead of loose sheets to be prepared with continuous serial number on each page in all contractual works.
2. The firm to be instructed for timely disposal of scraps as per contract conditions.
3. All wagons should be offered to the firm by completing the pre-inspection on the same day as the date of arrival/placement of wagons considering the available Railway infrastructure/facilities.

This issues with the approval of SDGM.

B K Mahanta
29.08.22
(B K Mahanta)

Dy. CVO(Mech)/ECOR/BBS