


Sub: Addendum & Corrigendum No.23 to G&SR Book(2012) and 28 to G&SR Book(2010) published by East Coast Railway

1. Existing SR.4.01.01 is to be substituted as under:

- (a) On seeing the timings at 1600 hrs on GPS clock provided at control office, the section controller on duty shall ring up the stations under his control and transmit the correct time. He shall also transmit the correct time to Sub/Area Control offices in the same division within his control jurisdiction.
- (b) Each Control Office, Sub/Area Control office and the stations will then check the time in the clock provided in their office. If required, they shall arrange to correct the time by the prescribed system provided in the clock. In case the time is adjusted, necessary entries shall be made in the Train Signal Register and Station Master's Diary immediately.

(Authority: Railway Board letter No.2020/Safety(A&R)/19/09, Dated-28.07.2020)

  
(P.K.Jena) 12.6.21

Principal Chief Operations Manager