

**Addendum and Corrigendum Slip No.1 (ACS-1) to ECoR USSOR-21**

<b>Item No.</b>	<b>Description of Item</b>	<b>Unit</b>	<b>Rate (₹)</b>
195040	Supplying and fixing of Anti-skid MS/Stainless steel chequered plates on un-ballasted deck bridge as per approved drawings, with matching grade stainless steel fasteners as directed by Engineer-in-charge, on new bridge or replacement of existing chequered plates on old bridge including removal of old chequered plates and stacking near approaches of bridge, clear from all infringement. <b>Note</b> : Joints of chequered plates shall not fall in between sleepers.		
195041	MS chequered plates 6 to 8mm thick on new bridge.	Kg	94.43
195042	MS chequered plates 6 to 8mm thick including removal of existing chequered plates on Bridges. <b>Note</b> : Payment shall be made only as per weight of new chequered plate fixed.	Kg	99.57
195043	Anti-skid stainless steel chequered plate conforming to latest IS:6911, ISS Symbol 409M with flat bottom and top pattern conforming to IS:3502, 1A with bead height of minimum 0.8mm – on New bridges.	Kg	221.35
195044	Fixing Anti-Skid stainless steel chequered plate conforming to latest IS:6911, ISS Symbol 409M with flat bottom and top pattern conforming to IS:3502, 1A with bead height of minimum 0.8mm including removal of existing chequered plates on existing Bridges. <b>Note</b> : Payment shall be made only as per weight of new Chequered Plate fixed.	Kg	226.49